

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Location photo

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Location photo

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Ruts moving sediment and erosion on access road. Looking up hill.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Ruts moving sediment and erosion on access road. Looking down hill.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Erosion rill on road side.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Erosion rill on road side.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Trash and sediment build up in ditch at county road and access road intersection.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Sediment build up in ditch at county road and access road intersection.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Sediment moving on to pavement.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Trash dumped on side of access road.

HOAGLUND W-33-2
Api: 05-045-06524
Inspection # 689701324



Trash dumped on side of access road.