

Inspection Photos

Loc#335540

Operator: Ursa

Inspection Number: 680102933

Inspection Date: 4/30/2018





Photo#1:

Overview of Location to Northeast. Tanks with "Out of Service" labels are stored on Location.

April 30, 2018



Photo#2:

Vegetation is progressing though there are still areas of bare ground.

April 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#335540



Photo#3:
Two Anchors not marked.

April 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#335540