

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2018

Submitted Date:

05/08/2018

Document Number:

675000516**FIELD INSPECTION FORM**

Loc ID 332514 Inspector Name: Duran, Alicia On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 247459      | WELL | PR     | 11/06/2003  | GW         | 123-15256 | HSR-MASSEY 5-31 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                          |       |            |
|--------------------|--------------------------|-------|------------|
| Type               | WEEDS                    |       |            |
| Comment:           | Weeds around wellhead    |       |            |
| Corrective Action: | Comply with Rule 603.f . | Date: | 05/18/2018 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |                                |       |  |
|--------------------|--------------------------------|-------|--|
| Type               | TANK BATTERY                   |       |  |
| Comment:           | Metal berm and livestock fence |       |  |
| Corrective Action: |                                | Date: |  |
| Type               | WELLHEAD                       |       |  |
| Comment:           | Panel                          |       |  |
| Corrective Action: |                                | Date: |  |
| Type               | SEPARATOR                      |       |  |
| Comment:           | Metal berm and livestock fence |       |  |
| Corrective Action: |                                | Date: |  |

**Equipment:**

|                     |     |       |                 |
|---------------------|-----|-------|-----------------|
| Type: Gas Meter Run | # 1 |       | corrective date |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |

|                                   |                                |  |       |
|-----------------------------------|--------------------------------|--|-------|
| Type: Bird Protectors             | # 3                            |  |       |
| Comment:                          |                                |  |       |
| Corrective Action:                |                                |  | Date: |
| Type: Horizontal Heated Separator | # 1                            |  |       |
| Comment:                          |                                |  |       |
| Corrective Action:                |                                |  | Date: |
| Type: Ancillary equipment         | # 2                            |  |       |
| Comment:                          | 1 Automation array; 1 scrubber |  |       |
| Corrective Action:                |                                |  | Date: |
| Type: Emission Control Device     | # 2                            |  |       |
| Comment:                          |                                |  |       |
| Corrective Action:                |                                |  | Date: |
| Type: Plunger Lift                | # 1                            |  |       |
| Comment:                          |                                |  |       |
| Corrective Action:                |                                |  | Date: |

**Tanks and Berms:**

|                    |          |          |                |         |        |       |
|--------------------|----------|----------|----------------|---------|--------|-------|
| Contents           | #        | Capacity | Type           | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1        | OTHER    | PBV FIBERGLASS |         | ,      |       |
| Comment:           | 210 BBLS |          |                |         |        |       |
| Corrective Action: |          |          |                |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |                                  |                     |                     |             |       |
|--------------------|----------------------------------|---------------------|---------------------|-------------|-------|
| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|                    |                                  |                     |                     |             |       |
| Comment:           | Shared berm with crude oil tank. |                     |                     |             |       |
| Corrective Action: |                                  |                     |                     |             | Date: |

|                    |   |          |           |         |                       |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CRUDE OIL          | 2 | 300 BBLS | STEEL AST |         | 40.270470,-104.712400 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |        |                    |      |             |           |         |    |               |    |
|----------------------|--------|--------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 247459 | Type:              | WELL | API Number: | 123-15256 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |                    |      |             |           |         |    |               |    |
| Comment:             |        | PR                 |      |             |           |         |    |               |    |
| Corrective Action:   |        |                    |      |             |           |         |    | Date:         |    |
| BradenHead           |        |                    |      |             |           |         |    |               |    |
| Comment:             |        | Plumbed to surface |      |             |           |         |    |               |    |
| Corrective Action:   |        |                    |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                              | URL   |
|--------------|--|---|
| 675000517    | Photos of tank battery site adn wellhead | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456544">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456544</a> |