

# Inspection Photos

05/09/2018

Operator: HRM RESOURCES II LLC - 10548

Location ID: 317081

Inspection Doc. Number: 682503318

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: HRM RESOURCES II LLC - 10548  
Location ID: 317081



**Photo 1:** Photo taken from the north end of the location, facing west. Photo shows what looks to be a fuel tank w/ pump containing diesel fluids appears to be leaking onto the pad. Fluids can be found over the trailer as well as ponding beneath.



**Photo 2:** Photo taken from the north end of the location. Photo shows what looks to be a fuel tank w/ pump containing diesel fluids appears to be leaking onto the pad. Fluids can be found over the trailer as well as ponding beneath.

Inspection Photos  
Operator: HRM RESOURCES II LLC - 10548  
Location ID: 317081



**Photo 3:** Photo taken from the southeast corner, of the north-central produced water pit. Photo shows hydrocarbons in the produced water pit.



**Photo 4:** Photo taken from the south end, of the north-central produced water pit. Photo shows hydrocarbons in the produced water pit.