

Inspection Photo
Benzel 6-11H(J12W)
API# 045-20326
Inspection # 689301083



Location photo # 1



Location photo # 2

**Inspection Photo
Benzel 6-11H(J12W)
API# 045-20326
Inspection # 689301083**



Location photo # 3, missing faded label



Location photo # 4, missing faded label

Inspection Photo
Benzel 6-11H(J12W)
API# 045-20326
Inspection # 689301083



Location photo # 5, slope erosion near retention pond



Location photo # 6, Hole in containmnet