

Inspection Photos
Location Name: UPRR 50 PAN AM D #5
Facility ID #241812



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: UPRR 50 PAN AM D #5
Facility ID #241812



Photo 3. Unmarked riser w/ no LO/TO