

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2018

Submitted Date:

05/04/2018

Document Number:

689301051**FIELD INSPECTION FORM**

Loc ID 335065	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 25 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>																																																																																																																																			
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Rocky, TEP</td> <td></td> <td>COGCCInspectionReports@terraep.com</td> <td><a href="#">All Inspections</a></td> </tr> </table>					Contact Name	Phone	Email	Comment	Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>																																																																																																																							
Contact Name	Phone	Email	Comment																																																																																																																																
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>																																																																																																																																
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>279770</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11083</td><td>CLOUGH RWF 434-14</td><td>PR</td></tr> <tr><td>280113</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11197</td><td>CLOUGH RWF 444-14</td><td>PR</td></tr> <tr><td>280114</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11198</td><td>CLOUGH RWF 433-14</td><td>PR</td></tr> <tr><td>280115</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11199</td><td>CLOUGH RWF 344-14</td><td>PR</td></tr> <tr><td>280116</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11200</td><td>CLOUGH RWF 544-14</td><td>PR</td></tr> <tr><td>280117</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11201</td><td>CLOUGH RWF 44-14</td><td>PR</td></tr> <tr><td>280118</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11202</td><td>CLOUGH RWF 333-14</td><td>PR</td></tr> <tr><td>280119</td><td>WELL</td><td>PR</td><td>08/06/2006</td><td>GW</td><td>045-11203</td><td>CLOUGH RWF 43-14</td><td>PR</td></tr> <tr><td>280120</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11204</td><td>CLOUGH RWF 533-14</td><td>PR</td></tr> <tr><td>280122</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11205</td><td>CLOUGH RWF 33-14</td><td>PR</td></tr> <tr><td>280123</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11206</td><td>CLOUGH RWF 543-14</td><td>PR</td></tr> <tr><td>280125</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11207</td><td>CLOUGH RWF 343-14</td><td>PR</td></tr> <tr><td>280126</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11208</td><td>CLOUGH RWF 443-14</td><td>PR</td></tr> <tr><td>280127</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11209</td><td>CLOUGH RWF 334-14</td><td>PR</td></tr> <tr><td>280129</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11210</td><td>CLOUGH RWF 534-14</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	279770	WELL	PR	06/08/2006	GW	045-11083	CLOUGH RWF 434-14	PR	280113	WELL	PR	06/08/2006	GW	045-11197	CLOUGH RWF 444-14	PR	280114	WELL	PR	06/08/2006	GW	045-11198	CLOUGH RWF 433-14	PR	280115	WELL	PR	06/08/2006	GW	045-11199	CLOUGH RWF 344-14	PR	280116	WELL	PR	06/08/2006	GW	045-11200	CLOUGH RWF 544-14	PR	280117	WELL	PR	06/08/2006	GW	045-11201	CLOUGH RWF 44-14	PR	280118	WELL	PR	06/08/2006	GW	045-11202	CLOUGH RWF 333-14	PR	280119	WELL	PR	08/06/2006	GW	045-11203	CLOUGH RWF 43-14	PR	280120	WELL	PR	06/08/2006	GW	045-11204	CLOUGH RWF 533-14	PR	280122	WELL	PR	06/08/2006	GW	045-11205	CLOUGH RWF 33-14	PR	280123	WELL	PR	06/08/2006	GW	045-11206	CLOUGH RWF 543-14	PR	280125	WELL	PR	06/08/2006	GW	045-11207	CLOUGH RWF 343-14	PR	280126	WELL	PR	06/08/2006	GW	045-11208	CLOUGH RWF 443-14	PR	280127	WELL	PR	06/08/2006	GW	045-11209	CLOUGH RWF 334-14	PR	280129	WELL	PR	06/08/2006	GW	045-11210	CLOUGH RWF 534-14	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																												
279770	WELL	PR	06/08/2006	GW	045-11083	CLOUGH RWF 434-14	PR																																																																																																																												
280113	WELL	PR	06/08/2006	GW	045-11197	CLOUGH RWF 444-14	PR																																																																																																																												
280114	WELL	PR	06/08/2006	GW	045-11198	CLOUGH RWF 433-14	PR																																																																																																																												
280115	WELL	PR	06/08/2006	GW	045-11199	CLOUGH RWF 344-14	PR																																																																																																																												
280116	WELL	PR	06/08/2006	GW	045-11200	CLOUGH RWF 544-14	PR																																																																																																																												
280117	WELL	PR	06/08/2006	GW	045-11201	CLOUGH RWF 44-14	PR																																																																																																																												
280118	WELL	PR	06/08/2006	GW	045-11202	CLOUGH RWF 333-14	PR																																																																																																																												
280119	WELL	PR	08/06/2006	GW	045-11203	CLOUGH RWF 43-14	PR																																																																																																																												
280120	WELL	PR	06/08/2006	GW	045-11204	CLOUGH RWF 533-14	PR																																																																																																																												
280122	WELL	PR	06/08/2006	GW	045-11205	CLOUGH RWF 33-14	PR																																																																																																																												
280123	WELL	PR	06/08/2006	GW	045-11206	CLOUGH RWF 543-14	PR																																																																																																																												
280125	WELL	PR	06/08/2006	GW	045-11207	CLOUGH RWF 343-14	PR																																																																																																																												
280126	WELL	PR	06/08/2006	GW	045-11208	CLOUGH RWF 443-14	PR																																																																																																																												
280127	WELL	PR	06/08/2006	GW	045-11209	CLOUGH RWF 334-14	PR																																																																																																																												
280129	WELL	PR	06/08/2006	GW	045-11210	CLOUGH RWF 534-14	PR																																																																																																																												

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279770	WELL	PR	06/08/2006	GW	045-11083	CLOUGH RWF 434-14	PR
280113	WELL	PR	06/08/2006	GW	045-11197	CLOUGH RWF 444-14	PR
280114	WELL	PR	06/08/2006	GW	045-11198	CLOUGH RWF 433-14	PR
280115	WELL	PR	06/08/2006	GW	045-11199	CLOUGH RWF 344-14	PR
280116	WELL	PR	06/08/2006	GW	045-11200	CLOUGH RWF 544-14	PR
280117	WELL	PR	06/08/2006	GW	045-11201	CLOUGH RWF 44-14	PR
280118	WELL	PR	06/08/2006	GW	045-11202	CLOUGH RWF 333-14	PR
280119	WELL	PR	08/06/2006	GW	045-11203	CLOUGH RWF 43-14	PR
280120	WELL	PR	06/08/2006	GW	045-11204	CLOUGH RWF 533-14	PR
280122	WELL	PR	06/08/2006	GW	045-11205	CLOUGH RWF 33-14	PR
280123	WELL	PR	06/08/2006	GW	045-11206	CLOUGH RWF 543-14	PR
280125	WELL	PR	06/08/2006	GW	045-11207	CLOUGH RWF 343-14	PR
280126	WELL	PR	06/08/2006	GW	045-11208	CLOUGH RWF 443-14	PR
280127	WELL	PR	06/08/2006	GW	045-11209	CLOUGH RWF 334-14	PR
280129	WELL	PR	06/08/2006	GW	045-11210	CLOUGH RWF 534-14	PR

<b>General Comment:</b> <a href="#">Routine Field Inspection</a>
---

### Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign peeling off of tank		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	07/04/2018

Emergency Contact Number:

Comment: 1-970-285-9377

Corrective Action:

Date:

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panel fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panel fencing		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Plunger Lift	# 15			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 8			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 16			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:					Date:	

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:	Centralized Battery					
Corrective Action:					Date:	

**Paint**

Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	

CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	279770	Type:	WELL	API Number:	045-11083	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280113	Type:	WELL	API Number:	045-11197	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280114	Type:	WELL	API Number:	045-11198	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280115	Type:	WELL	API Number:	045-11199	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280116	Type:	WELL	API Number:	045-11200	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280117	Type:	WELL	API Number:	045-11201	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280118	Type:	WELL	API Number:	045-11202	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280119	Type:	WELL	API Number:	045-11203	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280120	Type:	WELL	API Number: 045-11204 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280122	Type:	WELL	API Number: 045-11205 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280123	Type:	WELL	API Number: 045-11206 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280125	Type:	WELL	API Number: 045-11207 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280126	Type:	WELL	API Number: 045-11208 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280127	Type:	WELL	API Number: 045-11209 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID:	280129	Type:	WELL	API Number: 045-11210 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift			

Corrective Action:		Date:	
--------------------	--	-------	--

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB):	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Gravel				
Retention Ponds						
Rip Rap						
		Compaction				

Comment: [slope erosion on East end of location](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 06/04/2018

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401630397	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453422">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453422</a>
689301052	Inspection photo 689301052	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453413</a>