

Inspection Photo
Savage RWF 423-35
API# 045-18034
Inspection # 689301085



Location photo # 1



Location photo # 2

Inspection Photo
Savage RWF 423-35
API# 045-18034
Inspection # 689301085



Location photo # 3, Old concrete blanket next to transfer pump



Location photo # 4, Old concrete blanket

**Inspection Photo
Savage RWF 423-35
API# 045-18034
Inspection # 689301085**



Location photo # 5, Slope erosion on south end of tank battery.



Location photo # 6, Slope erosion on south end of tank battery.

Inspection Photo
Savage RWF 423-35
API# 045-18034
Inspection # 689301085



**Location photo # 7, Slope erosion on south
end of tank battery.**