

Inspection Photos
Location Name: Kehn USX AC #35-13
Location ID: 310264



Photo 1: Location, looking S



Photo 2: Wellhead, looking NW

Inspection Photos
Location Name: Kehn USX AC #35-13
Location ID: 310264



Photo 3: Stained soil at wellhead



Photo 4: Stained soil SE of tank battery berm