

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2018

Submitted Date:

05/08/2018

Document Number:

680102933**FIELD INSPECTION FORM**

Loc ID 335540	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 6 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																							
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																											
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Knudson, Dwayne</td> <td>970-456-3335</td> <td>dknudson@ursaresources.com</td> <td>All Inspections</td> </tr> </table>					Contact Name	Phone	Email	Comment	Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections																																																																															
Contact Name	Phone	Email	Comment																																																																																								
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections																																																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>289262</td><td>WELL</td><td>PR</td><td>01/01/2018</td><td>GW</td><td>045-13707</td><td>BURCKLE A1</td><td>RI</td></tr> <tr><td>289263</td><td>WELL</td><td>PR</td><td>07/07/2011</td><td>GW</td><td>045-13706</td><td>Burckle Federal A2</td><td>RI</td></tr> <tr><td>289264</td><td>WELL</td><td>PR</td><td>01/01/2018</td><td>GW</td><td>045-13705</td><td>BURCKLE A3</td><td>RI</td></tr> <tr><td>289997</td><td>WELL</td><td>PR</td><td>01/01/2018</td><td>GW</td><td>045-13960</td><td>BURCKLE A7</td><td>RI</td></tr> <tr><td>291710</td><td>WELL</td><td>PR</td><td>01/01/2018</td><td>GW</td><td>045-14516</td><td>BURCKLE A11</td><td>RI</td></tr> <tr><td>291712</td><td>WELL</td><td>PR</td><td>01/01/2018</td><td>GW</td><td>045-14515</td><td>BURCKLE A9</td><td>RI</td></tr> <tr><td>298250</td><td>WELL</td><td>PR</td><td>07/02/2011</td><td>GW</td><td>045-17096</td><td>BURCKLE FED CA A10</td><td>RI</td></tr> <tr><td>298251</td><td>WELL</td><td>PR</td><td>08/15/2011</td><td>GW</td><td>045-17097</td><td>BURCKLE FED CA A12</td><td>RI</td></tr> <tr><td>422091</td><td>WELL</td><td>PR</td><td>07/08/2011</td><td>GW</td><td>045-20490</td><td>Burckle Federal A14</td><td>RI</td></tr> <tr><td>422095</td><td>WELL</td><td>PR</td><td>08/15/2011</td><td>GW</td><td>045-20491</td><td>Burckle Federal A13</td><td>RI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	289262	WELL	PR	01/01/2018	GW	045-13707	BURCKLE A1	RI	289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	RI	289264	WELL	PR	01/01/2018	GW	045-13705	BURCKLE A3	RI	289997	WELL	PR	01/01/2018	GW	045-13960	BURCKLE A7	RI	291710	WELL	PR	01/01/2018	GW	045-14516	BURCKLE A11	RI	291712	WELL	PR	01/01/2018	GW	045-14515	BURCKLE A9	RI	298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	RI	298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	RI	422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	RI	422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																				
289262	WELL	PR	01/01/2018	GW	045-13707	BURCKLE A1	RI																																																																																				
289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	RI																																																																																				
289264	WELL	PR	01/01/2018	GW	045-13705	BURCKLE A3	RI																																																																																				
289997	WELL	PR	01/01/2018	GW	045-13960	BURCKLE A7	RI																																																																																				
291710	WELL	PR	01/01/2018	GW	045-14516	BURCKLE A11	RI																																																																																				
291712	WELL	PR	01/01/2018	GW	045-14515	BURCKLE A9	RI																																																																																				
298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	RI																																																																																				
298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	RI																																																																																				
422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	RI																																																																																				
422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	RI																																																																																				

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289262	WELL	PR	01/01/2018	GW	045-13707	BURCKLE A1	RI
289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	RI
289264	WELL	PR	01/01/2018	GW	045-13705	BURCKLE A3	RI
289997	WELL	PR	01/01/2018	GW	045-13960	BURCKLE A7	RI
291710	WELL	PR	01/01/2018	GW	045-14516	BURCKLE A11	RI
291712	WELL	PR	01/01/2018	GW	045-14515	BURCKLE A9	RI
298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	RI
298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	RI
422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	RI
422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	RI

General Comment: This is an Interim Reclamation & Stormwater focused Inspection, a Follow Up to Insp Doc#680100148 dated 9/18/15.

Inspected Facilities				
Facility ID: <u>289262</u>	Type: <u>WELL</u>	API Number: <u>045-13707</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>289263</u>	Type: <u>WELL</u>	API Number: <u>045-13706</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>289264</u>	Type: <u>WELL</u>	API Number: <u>045-13705</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>289997</u>	Type: <u>WELL</u>	API Number: <u>045-13960</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>291710</u>	Type: <u>WELL</u>	API Number: <u>045-14516</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>291712</u>	Type: <u>WELL</u>	API Number: <u>045-14515</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298250</u>	Type: <u>WELL</u>	API Number: <u>045-17096</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298251</u>	Type: <u>WELL</u>	API Number: <u>045-17097</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>422091</u>	Type: <u>WELL</u>	API Number: <u>045-20490</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>422095</u>	Type: <u>WELL</u>	API Number: <u>045-20491</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Fail

Comment _____

Corrective Action _____

Date **08/08/2018**Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Fail

Comment _____

Corrective Action _____

Date **06/20/2018**

1003b. Area no longer in use? PassProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? PassSubsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? InProduction areas have been stabilized? Pass

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured Pass80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment: Efforts have been made to resolve CAs from Previous Inspection. Vegetation is progressing though there are still areas of bare ground. Annual weeds that become Debris appear to have been controlled & overall, site is tidy & stable. Outer areas of Interim Reclamation have vigorous & well established vegetation.

Corrective Action _____

Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
Slope Roughening	Pass					areas of cut slope have been pocked
Compaction	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401632793	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4455787
680102956	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4455780