

Inspection Photos
Location Name: CARL R. DEEPE "C" 1
Facility ID # 241204



Photo 1. Wellhead



Photo 2. Tank battery. Unmarked unused riser.

Inspection Photos
Location Name: MARTIN T HART "H" 1
Facility ID # 241204



Photo 3. Unmarked unused riser near crude oil. NO LO/TO.



Photo 4. Unmarked unused riser near transfer pump. NO LO/TO.

Inspection Photos
Location Name: CARL R. DEEPE "C" 2
Facility ID #241204



Photo 5. Unmarked unused riser near heater treater