

Interim Reclamation Inspection

May 14, 2018

Operator: PDC ENERGY INC - #69175

API: 05-123-23409

Inspection Document #: 682403590

Weld County, CO

NENW Section 35 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 1. Photo taken of the northeast battery location, facing Southwest. Appears stormwater runoff from the battery location is causing rill erosion off location. There were no observed BMPs being implemented along the battery location to minimize erosion.

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 2. Photo taken from the northern battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 3. Photo taken from the central battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 4. Photo taken from a portion of the access road. Cattle guard in need of maintenance. A similar inspection will be sent to the other Operator that also uses this BMP and access road. Both Operator's will need to coordinate to perform the required maintenance for this BMP.