

Inspection Photos
Location Name: EIBERGER #32-36
Facility ID #251613



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: EIBERGER #32-36
Facility ID #251613



Photo 3. Stained soil around wellhead