



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Apr 27, 2018 4:19:30 PM MDT
Server Receive Date:	Apr 27, 2018 4:19:49 PM MDT
Reference Number:	20180427-1877623866
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Apr 27, 2018 4:19:25 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Apr 26, 2018
Well Name	SHORT, LYLE GAS UNIT A 1
API Number	50670691100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

removed Kochia skeletons