

Form Information

| | |
|----------------------|---|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Clay Elkins (celkins@gobrainstorm.net) |
| Submission Date: | May 1, 2018 7:12:30 AM MDT |
| Server Receive Date: | May 1, 2018 7:16:31 AM MDT |
| Reference Number: | 20180501-1877855321 |
| Location: | 3601 N 1st St, Bloomfield, NM 87413, USA May 1, 2018 7:11:29 AM MDT [View Map] |

Information

| | |
|-----------------|--|
| Name | celkins@gobrainstorm.net |
| Date | May 31, 2018 |
| Well Name | WEBB-REEDER GAS UNIT B 1 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Erosion Repairs Clean up Operator Debris Clean Up Land Owner Debris Clean Up Contaminated Soils Replaced/Repaired Well Sign |

Picture North to South



Picture South to North



Picture East to West



Picture West to East

