



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	May 1, 2018 7:23:20 AM MDT
Server Receive Date:	May 1, 2018 7:24:30 AM MDT
Reference Number:	20180501-1877855458
Location:	9 Rd 3227, Aztec, NM 87410, USA May 1, 2018 7:23:16 AM MDT [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Apr 25, 2018
Well Name	JOHNSON, MW GAS UNIT A 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Seeding Clean Up Weed Debris Clean Up Contaminated Soils

Picture North to South



Picture South to North



Picture East to West



Picture West to East

