

**Inspection Photo  
Federal RWF 23-8  
API# 045-12816  
Inspection # 689301113**



**Location Photo #1,**



**Location Photo #2, Erosion along access road  
near tank**



**Inspection Photo  
Federal RWF 23-8  
API# 045-12816  
Inspection # 689301113**



**Location Photo #3, Erosion on the back side of tank**



**Location Photo #4, erosion near the tank**

**Inspection Photo**  
**Federal RWF 23-8**  
**API# 045-12816**  
**Inspection # 689301113**



**Location Photo #5, Erosion near separator on  
South end**