

**Inspection Photo**  
**Juniper 2-9A (M1E)**  
**API# 045-16088**  
**Inspection # 689301121**



**Location Photo #1,**



**Location Photo #2, Faded Label on chemical tank**



**Inspection Photo**  
**Juniper 2-9A (M1E)**  
**API# 045-16088**  
**Inspection # 689301121**



**Location Photo #3, faded label on chemical tank**



**Location Photo #4, stain on location near tank battery**



**Inspection Photo  
Juniper 2-9A (M1E)  
API# 045-16088  
Inspection # 689301121**



**Location Photo #5, leaking gasket on tank**



**Location Photo #6, stained rock inside tank containment**



**Inspection Photo**  
**Juniper 2-9A (M1E)**  
**API# 045-16088**  
**Inspection # 689301121**



**Location Photo #7, stained rock inside tank containment**



**Location Photo #8, stained rock inside tank containment**



**Inspection Photo  
Juniper 2-9A (M1E)  
API# 045-16088  
Inspection # 689301121**



**Location Photo #9, stained rock inside tank containment**



**Location Photo #10, stained rock inside tank containment**



**Inspection Photo  
Juniper 2-9A (M1E)  
API# 045-16088  
Inspection # 689301121**



**Location Photo #11, stained rock inside tank containment**



**Location Photo #12, stained rock inside tank containment**