

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2018

Submitted Date:

05/17/2018

Document Number:

677900340

**FIELD INSPECTION FORM**

Loc ID 321958 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 72185  
Name of Operator: PRODUCTION MANAGEMENT INC  
Address: 5000 BUTTE ST #107  
City: BOULDER State: CO Zip: 80301

**Findings:**

- 17 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Warren, William	303-449-0557	williamwarren@hotmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285369	WELL	PR	11/21/2007	GW	017-07636	COE TRUST 21-18A	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by south tanks. Stickers on north water tank by VGS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by VGS		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	E-42 Ajax engine		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 6		
Comment:	Propane tank, chemical tank w/containment, day drum, telemetry equipment at meter shed, 2-gas scrubbers		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on south side of open top water tank		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter shed on west side of open top water tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		

Comment:	HHS on south side of meter shed			Date:	
Corrective Action:				Date:	
Type:	Pump Jack	#	1		
Comment:	A-912-DC Lufkin			Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		38.669800,-102.504260
Comment:	Open top water tank on east side of meter run				Date:
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		38.669610,-102.504280
Comment:	East steel tank is disposal tank				Date:
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		38.669610,-102.504680
Comment:	Green tank on south side of oil tanks used as overflow				Date:
Corrective Action:					Date:

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	Shared berms
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		38.669610,-102.504280

Comment:	2-Steel production tanks
Corrective Action:	Date:

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 285369 Type: WELL API Number: 017-07636 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT