



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush (*Chrysothamnus nauseosus*), crested wheatgrass (*Agropyron cristatum*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the northern portion of the project area from the northeastern corner of the working area facing westward.



Photo 4. View of post debris in eastern interim reclamation area.



Photo 5. View of musk thistle (*Carduus nutans*) growing within the area.