

# Construction and Stormwater Inspection

May 17, 2018

Operator: MAGPIE OPERATING, INC- #52530

Location ID: 333081

Inspection Document #: 682403592

Larimer County, CO

SENW Section 32 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bunker 3A /Pad  
Location ID: 333081



**Photo 1.** Photo taken from a portion of the access road, facing East. Operator has installed a tracking device BMP.



**Photo 2.** Photo taken from the northwestern perimeter of location, facing South. During this inspection, a ditch and berm BMP was being installed around the entire perimeter of the location. Operator was not finished installing the BMP, as the soil moisture was affecting the implementation of installing each BMP.

Inspection Photos  
Location Name: Bunker 3A /Pad  
Location ID: 333081



**Photo 3.** Photo taken from the western perimeter of the location, facing South. See comments under Photo 2.



**Photo 4.** Photo taken from the northeast perimeter of the location, facing North. See comments under Photo 2.



Inspection Photos  
Location Name: Bunker 3A /Pad  
Location ID: 333081



**Photo 5.** Photo taken from the soil pit dug around the central location. Topsoil depth was approximately 15", not 6". Operator shall comply with Rule 1002.b.(1) throughout the entire disturbance area.