



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush (*Chrysothamnus nauseosus*), crested wheatgrass (*Agropyron cristatum*), and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the southern portion of the project area from the northwestern corner facing eastward.



Photo 4. View of vegetated culvert outlet in the southeastern project area.



Photo 5. View of the eastern portion of the project area from the northeastern project area facing southward.



Photo 6. View of marker debris in the northwestern project area.