



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing on cut-slopes, but sparse on steep areas, with rilling evident.**



**Photo 3. View of the southern portion of the project area from the southwestern corner facing southeastward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and sand dropseed (*Sporobolus cryptandrus*).**



**Photo 4. View of Scotch thistles (*Onopordum acanthium*) within the interim reclamation area.**