

Inspection Photos
Location Name: Cornish Off-site Tank Battery
Location ID: 437140



Photo 1: Location, looking NE



Photo 2: Faded tank stenciling on condensate tank

Inspection Photos
Location Name: Cornish Off-site Tank Battery
Location ID: 437140



Photo 3: Stormwater erosion SW of ECD, looking NE.



Photo 4: Stormwater erosion S of ECD, looking N.