

Inspection Photos
Location Name: Cornish #17-11
Location ID: 306192



Photo 1: Location, looking SW



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Cornish #17-11
Location ID: 306192



Photo 3: Stained soil at loadout fitting



Photo 4: Stained soil at separator

Inspection Photos
Location Name: Cornish #17-11
Location ID: 306192



Photo 5: Stained soil at wellhead