

Inspection Photos

Loc# 449874

Operator: Laramie

Inspection Number: 674104411

Inspection Date: 5/14/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Southeast section of cut slope where stabilization is needed.

May 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#449874



Photo#2:
Close up of SE section of Cut Slope.



Photo#3
View of Sediment flow away from Cut Slope.

May 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#449874



Photo#4:

View of Silt fence installed along base of Fill Slope, protecting and segregating Topsoil .

May 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#449874