

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2018

Submitted Date:

05/21/2018

Document Number:

688301834**FIELD INSPECTION FORM**
 Loc ID 451166 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator
ConocoPhillips		COPColoradoReg@conocophillips.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451167	WELL	DG	03/02/2018		001-10073	Big Sandy 3-65 36-31 2CH	DG
453493	WELL	DG	03/01/2018		001-10101	Big Sandy 3-65 36-31 2AH	DG

General Comment:Frac Inspection

Inspected FacilitiesFacility ID: 451167 Type: WELL API Number: 001-10073 Status: DG Insp. Status: DG**Well Stimulation**Stimulation Company: HalliburtonStimulation Type: OTHER**Observation:**Other: Xlink

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: 0

Frac Flow Back: Fluid: _____ Gas: _____

Comment: AH and CH are being zippered.Stage 2 CH, 10 pumps, BHd 0 psi, Pressure test 9552 psi, ISIP (before sand) 4431, shut down at acid due to leak. Shelter warning due to lightning-did not stay for whole frac.

Corrective Action: _____

Date: _____

Facility ID: 453493 Type: WELL API Number: 001-10101 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass	Spill Response	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301840	Conoco Phillips Big Sandy 3-65 36-31 sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470091