

Inspection Photos

Location Name: Sitzman 1 Tank Battery Spill ID: 454307, API: 05-123-11421

Complaint #200445872 Inspection Date: 05/22/2018



Photo 1 – View of spigot sampling point for well permit no. 276778.



Photo 2 –View of water well vault for water well permit no. 276778 with new well seal, pump/motor and pressure tank.



Inspection Photos

Location Name: Sitzman 1 Tank Battery Spill ID: 454307, API: 05-123-11421

Complaint #200445872 Inspection Date: 05/22/2018



Photo 3 – View of initial purge water with sediment load.



Photo 4 - View of excavation located southeast of water well permit no. 276778. Viewing southeast.



Inspection Photos

Location Name: Sitzman 1 Tank Battery Spill ID: 454307, API: 05-123-11421

Complaint #200445872 Inspection Date: 05/22/2018



Photo 5 – Viewing excavation from east of work area. Picture is viewing northwest. Excavation is located beyond fence. Dairy barn with adjacent water well permit no. 276778 is visible in upper left.



Photo 6 – View of non-impacted stockpiles, south of excavation area.

