

Inspection Photos  
Location Name: SHABLE #17-15G  
API: 05-123-15235



Weeds and unused equipment before



Methanol tank removed but weeds have overgrown.