

**Inspection Photo
Burkle A-9
API# 045-14515
Inspection # 689301168**



Location Photo #1



Location Photo #2

**Inspection Photo
Burkle A-9
API# 045-14515
Inspection # 689301168**



Location Photo #3, Peeling signs on tanks

**Inspection Photo
Burkle A-9
API# 045-14515
Inspection # 689301168**



Location Photo #4, Slope erosion behind tank battery

Location Photo #5, slope erosion behind tank battery.

**Inspection Photo
Burkle A-9
API# 045-14515
Inspection # 689301168**



Location Photo #6, soil build up from slope erosion.

Location Photo #7, Slope erosion behind tank battery