

Inspection Photo
Hangs B3
API# 045-12190
Inspection # 689301180



Location Photo #1



Location Photo #2

Inspection Photo
Hangs B3
API# 045-12190
Inspection # 689301180



**Location Photo #3, Stained material in
containment**