

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2018

Submitted Date:

05/22/2018

Document Number:

688400182

FIELD INSPECTION FORM

Loc ID 451659 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 5950 CEDAR SPRINGS ROAD
City: DALLAS State: TX Zip: 75235

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beecherl, Arthur	214-838-2783	Regulatory@verdadoil.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451673	WELL	DG	09/07/2017		123-45162	WARNER 01N-64W-17-1H	WO
451674	WELL	DG	09/05/2017		123-45163	WARNER 01N-64W-17-2H	WO

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type LOCATION		
Comment:	Approx 32' sound walls on North and west end of location		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 451673 Type: WELL API Number: 123-45162 Status: DG Insp. Status: WO

Facility ID: 451674 Type: WELL API Number: 123-45163 Status: DG Insp. Status: WO

Complaint

Comment:

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 4-22-2018

Complaint Contacted:

Date: 4-22-2018 Time 1300 Hrs

Location #: 451659

Inspection Document #: 688400181

Nature of complaint: NOISE

Field Inspector Actions:

On 4-23-26-2018, I was contacted by COGCC staff in reference to some complaint received by the COGCC in reference to noise. The complaint stated the issues were occurring in the Keensburg area.

On 4-23-2018 I made contact with the complaint who indicated she was experiencing noise coming from what she believed was the Verdad Warner location. I performed a complete site inspection of the location. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. Due to high winds in the area we were unable to run sound study at time of the inspection.

No violation of COGCC rules were observed at the time of the inspection of the frack operation nor in the surrounding neighborhood.

All information reviewed and site inspection information were submitted to the complaint specialist for further review

Corrective Action:

Date:

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: _____

Corrective Action: _____

Date: _____