

# Final Reclamation Inspection

May 21, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-15199

Inspection Document #: 682403623

Weld County, CO

NESE Section 36 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-CARROLL #9-36  
API: 05-123-15199



**Photo 1.** Photo taken from the well location, facing South. Photo illustrates no vegetative growth at the well location.



Inspection Photos  
Location Name: HSR-CARROLL #9-36  
API: 05-123-15199



**Photo 2.** Photo taken from a portion of the access road, facing North. Photo illustrates no vegetative growth or stunted growth along the access road.