

Final Reclamation Inspection

May 21, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-14758

Inspection Document #: 682403625

Weld County, CO

NENE Section 35 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BERIG UPRR #41-35 #2
API: 05-123-14758



Photo 1. Photo taken along a portion of the access road, facing Southeast. Photo illustrates equipment left on location (meter shed).

Inspection Photos
Location Name: BERIG UPRR #41-35 #2
API: 05-123-14758



Photo 2. Photo taken from the battery location, facing South. Active remediation project still open. Operator shall comply with applicable Reclamation rules and regulations during the remediation process (i.e., weed and stormwater management).