

Inspection Photos
Location Name: Foss USX AA #5-25
API: 05-123-24562



Photo 1: Location



Photo 2: Wellhead, weeds at wellhead

Inspection Photos
Location Name: Foss USX AA #5-25
API: 05-123-24562



Photo from prior inspection for comparison



Photo 3: Unused equipment removed

Inspection Photos
Location Name: Foss USX AA #5-25
API: 05-123-24562



Photo 4: Stained soil at truck loadout