

# Construction and Stormwater Inspection

May 23, 2018

Operator: MAGPIE OPERATING, INC- #52530

Location ID: 333081

Inspection Document #: 682403629

Larimer County, CO

SENW Section 32 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Bunker 3A /Pad  
Location ID: 333081



**Photo 1.** Photo taken from the northeastern perimeter of location, facing East. Operator has installed a silt fence BMP around the entire perimeter of the location. Operator still plans to install a sediment trap and make repairs to the ditch and berm BMP.



**Photo 2.** Photo taken from the northwestern perimeter of location, facing Southwest. See comments under Photo 1.



Inspection Photos  
Location Name: Bunker 3A /Pad  
Location ID: 333081



**Photo 3.** Photo taken from the southwestern perimeter of the location, facing East. Photo illustrates the southern topsoil stockpile that has been temporarily stabilized with equipment tracking.



**Photo 4.** Photo taken from the southwestern perimeter of the location, facing North. Photo illustrates the cut from topsoil salvage operations.

Inspection Photos  
Location Name: Bunker 3A /Pad  
Location ID: 333081



**Photo 5.** Photo taken from the southeastern perimeter of the location, facing North. Photo illustrates the eastern topsoil stockpile that has been temporarily stabilized with equipment tracking.