

**Inspection Photos**  
**Location Name: Top Operating – Rider #1**  
**Facility ID: 10507, Remediation Project: 11300**  
**Inspection Date: 05/17/2018**



**Photo #1 – Geoprobe**



**Photo #2 – Gauging monitoring wells prior to using Geoprobe**

## Inspection Photos

Location Name: Top Operating – Rider #1

Facility ID: 10507, Remediation Project: 11300

Inspection Date: 05/17/2018



**Photo #3 – Soil sample logging & field screening**



**Photo #4 – Soil sample included a hydrocarbon smear zone**



## Inspection Photos

Location Name: Top Operating – Rider #1

Facility ID: 10507, Remediation Project 11300

Inspection Date: 05/17/2018



**Photo #5 – Soil sample including hydrocarbon smear zone**



**Photo #6 – Soil samples selected for lab analysis being stored in a cooler, on ice.**

