

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2018

Submitted Date:

05/24/2018

Document Number:

688500070

FIELD INSPECTION FORM

Loc ID 321290 Inspector Name: CANFIELD, CHRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
HERRING, MURRAY J	(303) 727-9915 x203	murray.herring@topoperating.com	
Deranleau, Greg		greg.deranleau@state.co.us	
Axelson, John		john.axelson@state.co.us	
HERRING, PAUL	(303) 727-9915	paul.herring@topoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
321290	LOCATION	CL			-	RIDER FAMILY TRUST-63N69W 36NESE	EI

General Comment:

Inspection for the purpose of observing field work done by the operator under approved Form 27 Document #401621714 (REM #11300)

Inspected Facilities

Facility ID: 321290 Type: LOCATION API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: Field observations, including field screening of soil samples collected from multiple soil borings, indicate two (2) historical releases; one (1) in the vicinity of a former horizontal separator, the other at the location of a former partially-buried vessel. Hydrocarbon impacts were observed both within the capillary fringe and below the water table. Field work done on 05/17/2018 did not determine the extent of impacts from either release.

Corrective Action: Submit Form 19 Spill/Release Report concerning discovery of a historical release near the former horizontal separator. Submit Form 19 Spill/Release Report concerning discovery of a historical release at the former partially-buried vessel. Submit a Form 27 Supplemental Site Investigation Work Plan proposing necessary work to delineate the extent of impacts to soils and ground water. Date: 06/08/2018

Reportable: YES GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: 9

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500071	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4474249