

# Final Reclamation and Stormwater Inspection

May 22, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 318780

Inspection Document #: 674902122

Weld County, CO

SWNW Section 12 T1N R67W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1N67W12  
Location ID: 318780



**Photo 1.** Photo taken from the location, facing North. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows, straw crimped mulch, and some perennial grass starting to grow.



**Photo 2.** Photo taken from the location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: KERR MCGEE /1N67W12  
Location ID: 318780



**Photo 3.** Photo taken from the facility area, facing East. along the access road. See comments under Photo 1.



**Photo 4.** Photo taken along east edge of disturbance area, facing North. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at low densities.