

Final Reclamation and Stormwater Inspection

May 22, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336256

Inspection Document #: 674902123

Weld County, CO

SWSW Section 12 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N67W12
Location ID: 336256



Photo 1. Photo taken from the location, facing Northeast. Appears the Operator has removed all equipment from the well pad locations. Thick layer of manure and mulch is covering parts of the previous disturbance area. No evidence of reclamation or seeding activity observed in other parts of the location.



Photo 2. Photo taken from the location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1N67W12
Location ID: 336256



Photo 3. Photo taken from the location, facing South into the access road and tank battery. Equipment left on site. See comments under Photo 1.



Photo 4. Photo taken along access road from the tank battery towards the well locations, facing Northwest.