

Inspection Photo
Graham 32-12A
API # 045-09365
Inspection # 689301214



Location Photo #1



Location Photo #2

**Inspection Photo
Graham 32-12A
API # 045-09365
Inspection # 689301214**



Location Photo #3, Missing label on chemical tank



Location Photo #4, Missing label on chemical tank