

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2018

Submitted Date:

05/24/2018

Document Number:

688500070**FIELD INSPECTION FORM**Loc ID 321290 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 39560Name of Operator: TOP OPERATING COMPANYAddress: 3609 S WADSWORTH BLVD STE 340City: LAKEWOOD State: CO Zip: 80235**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
HERRING, MURRAY J	(303) 727-9915 x203	murray.herring@topoperating.com	
Axelson, John		john.axelson@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
HERRING, PAUL	(303) 727-9915	paul.herring@topoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
321290	LOCATION	CL			-	RIDER FAMILY TRUST- 63N69W 36NESE	EI

**General Comment:**

Inspection for the purpose of observing field work done by the operator under approved Form 27 Document #401621714 (REM #11300)



**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Field observations, including field screening of soil samples collected from multiple soil borings, indicate two (2) historical releases; one (1) in the vicinity of a former horizontal separator, the other at the location of a former partially-buried vessel. Hydrocarbon impacts were observed both within the capillary fringe and below the water table. Field work done on 05/17/2018 did not determine the extent of impacts from either release.

Corrective Action: Submit Form 19 Spill/Release Report concerning discovery of a historical release near the former horizontal separator. Submit Form 19 Spill/Release Report concerning discovery of a historical release at the former partially-buried vessel. Submit a Form 27 Supplemental Site Investigation Work Plan proposing necessary work to delineate the extent of impacts to soils and ground water.

Date: 06/08/2018

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water:

Depth to Ground Water: 9

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401652964	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4474250">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4474250</a>
688500071	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4474249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4474249</a>