

**Inspection Photos**  
**Location Name: Nielson #4**  
**API: 05-007-06117**



**Nielson #4 well head and electric pump jack.**



**Stained soil at well head. Noted on previous inspection.**



**Inspection Photos**  
**Location Name: Nielson #4**  
**API: 05-007-06117**



**Well head and surrounding soil stained with oil.**



**Nielson #4 AST.**