

Inspection Photos  
Location Name: Smith Rancho 1-14  
API: 05-107-06046



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. Gravel stored on location.**

Inspection Photos  
Location Name: Smith Rancho 1-14  
API: 05-107-06046



**Photo 3. Stained soil and absorbent pads at wellhead.**



**Photo 4. Close-up of wellhead and absorbent pads.**