



Photo 1. View of well marker and unknown pipe.



Photo 2. View of pipeline riser at 37.12842, -107.00692 (lat./long.) that needs to be removed.



Photo 3. View of Russian thistles (*Acroptilon repens*) within the project area. Approximately 200 individuals observed.



Photo 4. View of musk thistles (*Carduus nutans*) within the project area. Approximately 200 individuals observed, both dry and flowered from previous season and vegetative in the current growing season.



Photo 5. View of the western portion of the project area from the northwestern edge facing southward.





Photo 6. View of the project area from the northwestern edge facing center.



Photo 7. View of the northern portion of the project area from the northwestern edge facing eastward.