

Final Reclamation Inspection

May 31, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-08199

Inspection Document #: 682403637

Weld County, CO

SWNE Section 27 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: VALLEY 66 UNIT #1
API: 05-123-08199



Photo 1. Photo taken from the battery location, facing South. Photo illustrates equipment left on location (meter shed) that needs to be removed. Operator shall conduct final reclamation activities per Rule 1004 by 1/12/2019 and remove equipment ASAP.

Inspection Photos
Location Name: VALLEY 66 UNIT #1
API: 05-123-08199



Photo 2. Photo taken from the well location, facing North. Well has been plugged and abandoned. Operator shall conduct final reclamation activities per Rule 1004 by 7/27/2018.

Inspection Photos
Location Name: VALLEY 66 UNIT #1
API: 05-123-08199



Photo 3. Photo taken from the battery location, facing North. Access road remains. Operator shall conduct final reclamation activities per Rule 1004 by 1/12/2019.