

Final Reclamation and Stormwater Inspection

May 28, 2018

Operator: PAR PACIFIC HOLDINGS INC # 16800

Location ID: 327424

Inspection Document #: 674902141

Weld County, CO

NESW Section 32 T1N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PAR PACIFIC /1N65W32
Location ID: 327424



Photo 1. Photo taken from the location, facing West. Appears the Operator has performed final reclamation activities, with all equipment removed, location re-contoured and several years of crop production observed through historical aerial imagery. A List C Colorado Noxious weed species, cheatgrass (*Bromus tectorum*), is found throughout the reclaimed area in moderate to high densities.



Photo 2. Photo taken from the adjacent reference location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: PAR PACIFIC /1N65W32
Location ID: 327424



Photo 3. Photo taken from the location. Several large patches of *Kochia scoparia*, a weedy annual, was observed throughout the reclaimed area.



Photo 4. Photo taken from the location, facing East. Several large patches of cheatgrass, a List C Colorado Noxious weed species, was observed throughout the reclaimed area.