

# Final Reclamation and Stormwater Inspection

May 28, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319948

Inspection Document #: 674902142

Adams County, CO

SWNE Section 5 T1S R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 319948



**Photo 1.** Photo taken from the location, facing West. Appears the Operator has performed final reclamation activities at the well site and access road to the facility. The concrete slab was left on location.



**Photo 2.** Photo taken from the location, facing Southeast. The facility has not been reclaimed and there is equipment left on site and current work activities.

Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 319948



**Photo 3.** Photo taken from the location, facing South.  
See comments under Photo 2.



**Photo 4.** Photo taken from the location, facing South.  
See comments under Photo 2.



Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 319948



**Photo 5.** Photo taken from the location, facing South.  
See comments under Photo 2.



**Photo 6.** Photo taken along access road from facility  
leaving location, facing South.

Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 319948



**Photo 7.** Photo taken along the north side of the access road from facility leaving location. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at low densities.