

Final Reclamation and Stormwater Inspection

May 28, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 320377

Inspection Document #: 674902145

Adams County, CO

NESW Section 5 T1S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1S65W5
Location ID: 320377



Photo 1. Photo taken from the location entrance, facing West. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows, straw crimped mulch, and perennial grass starting to come in.




Photo 2. Photo taken from the location along the access road. See comments under Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1S65W5
Location ID: 320377



Photo 3. Photo taken from the location, facing North showing a barren patch of the disturbance area where reclamation has failed. See comments under Photo 1.



Photo 4. Photo taken along North edge of disturbance area showing the barren ground and potential salt issues.

Inspection Photos
Location Name: KERR MCGEE /1S65W5
Location ID: 320377



Photo 5. Photo taken from the location. See comments under Photo 1.



Photo 6. Photo taken within disturbance area. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at low densities.