

# Final Reclamation and Stormwater Inspection

May 28, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 320364

Inspection Document #: 674902146

Adams County, CO

SWSE Section 5 T1S R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 320364



**Photo 1.** Photo taken from the location entrance, facing North showing the facility location. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows, straw crimped mulch, and perennial grass starting to come in.



**Photo 2.** Photo taken from the location along the access road, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 320364



**Photo 3.** Photo taken from the location, facing North showing a barren patch of the disturbance area where reclamation has not been as successful. See comments under Photo 1.



**Photo 4.** Photo taken along access road, facing North. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at high densities along the access road and on location.